25X1A Approved For Rel	éa CLASSIFIED !	VESSAGE 9BOO	369P4	0030003089	Atric	
ORIG:				B/DPD	4 OPS/DP	
UNIT: MS/DED-DD/P	BECR	E T		C/DPD	5 RI/DFD	
EXT : 3118	ROUTING		3 6	/OPS/DPD	6	
DATE: 30 MOV 1960 772	HOUTING					
70 : 25X1A	CH/OPS BR					
25X1A —	СОММО	1				
FROM: DIRECTOR	TECH					
	CHALLE OPS	29	É	DEFERRED	PRIORITY	INITIALS
CONF: UPD (1,2,3,4,5,6,7,8,5	PROJUJE 1	7]		-		INITIALS
INFO: 8/C (11)	PROJECT		I	ROUTINE	OPERATIONAL IMMEDIATE	
DHD	AIR SUPPORT	,				
עחע	CHTEL			4	<b>OUT765</b>	מת
TOR: 2022Z 30 NOV 60				¥	001100	
· · · · · · · · · · · · · · · · · · ·	CONTROL					
to : 25X1A	FO T	25X1A		CITÉ:		
		AD I		25X	<sup>⊥</sup> 533	B
MEF: A. " 019 (IM 379;	CONTIAL WHEN RE			(1) 23/		
25X1A. 0566 (III a	ACTION .			Γ		
20/1/3 0506 (III &	1090ch: not same	- CAME				

- 1. ACTION TO PRECLUDE CONDITION EXISTING REF A TAKEN AS INDICATED HEP B.
- 2. PARA SIX REF B INDICATED FOLLOWING ACTION BY ALL ASSIGNED UNITS:
- A. MAKE ONE TIME LEAK CHECK OF BACK ACTT CXYCEN SYSTEM AT 1800 PER OR HETZER. PAY PARTICULAR ATTH TO COMSOLE ASSY. ANY LEAKAGE OUT OF RELIEF VALVE ON PRESSURE REDUCER IS CAUSE FOR REJECTION.
- B. SEED SPAKE PRESSURE REDUCERS (PM4300000-3 AND -1) AND PRESSURE SWITCHES (PE7000 AND 7000-1) TO FIREWEL FOR SPECIAL INSPECTION.
  - C. IESTALL INSPECTED PRESSURE REDUCERS AS SOON AS PRACTICABLE.
  - D. CAUTION PILOTS ABOUT SMOKING IN ACET AT ANY TIME.
- 3. FOR MAS EXPENIENCED NUMEROUS DEFICIENCIES IN THE OXYGEN AREA, MONEYER,
  THE PROJECT HAS BEEN EXTREMELY FORTUNATE TO DATE. IT IS THE CONSENSUS OF
  OPINION THAT THE QUALITY OF MAINTENANCE BRIES PERFORMED ON ASSIGNED ARTICLES IS
  SUPERIOR RESULTING IN MEGLICIBLE INCIDENTS.

25X1A		100	END OF	MESSAGE			
	OPS/DPD_	1000 OC	ORDINATING	OFFICERS			
RELEASING OFFICER			5-2-C-R	Z-T		Atstw	ENTICATING OFFICER
	ንረዓሳሪቪላ <sub>የ</sub> ደረ	<b>OFFERY</b>	YZK8741	ISSUM	*8FP8E	SPROMINI	